



11 / 12

FIG. 13


$$\left(\begin{array}{cccccccccc} P & P & 0 & 0 & 0 & 0 & P & P & P & P \\ P & P & P & P & P & 0 & 0 & 0 & 0 & P \\ P & P & P & P & 0 & P & 0 & 0 & P & 0 \\ P & P & P & 0 & P & P & 0 & P & 0 & 0 \\ P & P & 0 & P & P & P & P & 0 & 0 & 0 \end{array} \right)$$

FIG. 14A
 PRIOR ART

$$H = \left(\begin{array}{cccccccc} 1 & 2 & 3 & 4 & 5 & 6 & 7 & 8 \\ 1 & 0 & 0 & 1 & 0 & 1 & 1 & 1 \\ 0 & 1 & 1 & 1 & 0 & 1 & 0 & 1 \\ 1 & 1 & 0 & 1 & 1 & 0 & 0 & 0 \\ 1 & 0 & 1 & 0 & 1 & 0 & 1 & 1 \end{array} \right) \begin{array}{l} 1 \\ 2 \\ 3 \\ 4 \\ 4 \end{array}$$

PARTITY CHECK MATRIX H

FIG. 14B
 PRIOR ART



TANNER GRAPH G